

PRELIMINARY SCHEDULE OF EVENTS

<i>DATE</i>	<i>TIME</i>	<i>LOCATION</i>
Sunday, August 14		
2 to 6 p.m.	Registration	Cliff Lodge, Ballroom Lobby
6 to 7 p.m.	Welcome Reception	Cliff Lodge, Golden Cliff/Eagle's Nest
Monday, August 15		
7 a.m. to 5 p.m.	Registration	Cliff Lodge, Ballroom Lobby
8 a.m. to noon	PWR Primary – I	Cliff Lodge, Ballroom I
8 a.m. to noon	BWR SCC & Modeling – I	Cliff Lodge, Ballroom II
1:30 to 5:30 p.m.	PWR Primary – II	Cliff Lodge, Ballroom I
1:30 to 5:30 p.m.	BWR SCC & Modeling – II	Cliff Lodge, Ballroom II
Tuesday, August 16		
7:30 a.m. to 12:30 p.m.	Registration	Cliff Lodge, Ballroom Lobby
8 to 10 a.m.	PWR Primary – III	Cliff Lodge, Ballroom I
8 to 10 a.m.	LAS & RPV Steel	Cliff Lodge, Ballroom II
8 a.m. to noon	Super Critical Water-Cooled Reactors	Cliff Lodge, Ballroom III
10:30 a.m. to noon	Zircaloy	Cliff Lodge, Ballroom I
10:30 a.m. to noon	Operational Experience I	Cliff Lodge, Ballroom II
4 to 8 p.m.	Registration	Cliff Lodge, Ballroom Lobby
6 to 8 p.m.	Noble Metal & SCC Mitigation	Cliff Lodge, Ballroom I
6 to 8 p.m.	Operational Experience II	Cliff Lodge, Ballroom II
Wednesday, August 17		
7:30 a.m. to 5 p.m.	Registration	Cliff Lodge, Ballroom Lobby
8 a.m. to noon	PWR Secondary – I	Cliff Lodge, Ballroom I
8 a.m. to noon	IASCC - I	Cliff Lodge, Ballroom II
1:30 to 5:30 p.m.	PWR Secondary – II	Cliff Lodge, Ballroom I
1:30 to 3:30 p.m.	IASCC - II	Cliff Lodge, Ballroom II
4 to 5:30 p.m.	Crack Growth	Cliff Lodge, Ballroom II
6:30 to 9:30 p.m.	Conference Banquet	La Caille
Thursday, August 18		
7:30 a.m. to 2 p.m.	Registration	Cliff Lodge, Ballroom Lobby
8 a.m. to noon	Ni-Base Alloys – I	Cliff Lodge, Ballroom I
8 a.m. to noon	Irradiation Effects	Cliff Lodge, Ballroom II
1:30 to 5:30 p.m.	Ni-Base Alloys – II	Cliff Lodge, Ballroom I
1:30 to 3:30 p.m.	Waste Materials & Mechanical Properties	Cliff Lodge, Ballroom II