CREEP LIFE ESTIMATION OF SERVICE EXPOSED ALLOY 625 AMMONIA CRACKER TUBES

M.D.Mathew¹, K.Bhanu Sankara Rao¹, S.L.Mannan¹, K.Paknikar² and Raghubir Singh³

¹ Indira Gandhi Centre for Atomic Research, Kalpakkam - 603 102, India ² Heavy Water Board, Bombay - 400 094, India ³ National Metallurgical Laboratory, Jamshedpur - 831 007, India

Abstract

Creep properties of service exposed ammonia cracker tubes of Alloy 625 have been studied after a re-solution annealing treatment at 1433 K for one hour. The tubes were retrieved after 60,000 hours of operation at 993 K and gas pressure of 14 MPa. Creep properties of the re-solution annealed material were evaluated to assess the suitability of these tubes for reuse as cracker tubes. Estimation of rupture life has been carried out using iso-stress and Larson-Miller parameter methods. Creep rupture strength and rupture ductility recovered substantially on re-solution annealing. Metallographic studies showed extensive precipitation of delta phase at test temperatures below 1023 K.

> Superalloys 718, 625, 706 and Various Derivatives Edited by E.A. Loria The Minerals, Metals & Materials Society, 1997

Introduction

Alloy 625 is a solid solution strengthened nickel base superalloy containing substantial amounts of chromium (20-23 wt%), molybdenum (8-10 wt%), iron (5 wt% max.) and niobium (3.15-4.15 wt%). The aluminium and titanium additions are properly adjusted for refining purposes and are intentionally kept low compared to alloys like Alloy 718. In view of its excellent resistance to severely corrosive environments and good high temperature mechanical properties, this alloy was chosen for ammonia cracker tubes in heavy water plants where ammonia is cracked into nitrogen and hydrogen. During normal service, the cracker tubes are exposed to a temperature of about 993 K and gas pressure of 14 MPa. At these conditions, the tubes undergo creep deformation. Although the design life of the tubes was 100,000 hours, some failures have taken place after about 60,000 hours of service necessitating premature replacement of the cracker tubes. Since replacement of all the tubes is very expensive, studies have been underway to extend the life of the service exposed tubes through a rejuvenation heat treatment. A re-solution annealing treatment at 1433 K for one hour has been found beneficial with respect to tensile properties. The yield strength of the material declined from 927 MPa after service to 470 MPa on re-solution annealing compared to 352 MPa for virgin material. The tensile elongation increased from 6% after service to 55% after re-solution treatment compared to 53% recorded for virgin material. In this paper, the creep properties of the resolution annealed tubes evaluated by isostress method and Larson-Miller Parameteric method are presented. The creep behaviour of re-solution annealed tubes has been rationalised on the basis of the microstructural changes. The remanent creep life of rejuvenated tubes has been assessed.

Experimental

The present investigation has been carried out using one of the cracker tubes which failed after 60,000 hours of service. The tube had a length of 13.5 m with an outside diameter of 88.9 mm and wall thickness of 7.95 mm. Rectangular specimens of 25 mm gauge length, 7 mm width and 4 mm thickness were machined from the tube midwall in the longitudinal direction. Two series of creep rupture tests (named series I and series II) were conducted for determining the residual creep life. The series I tests were isostress tests conducted at six different temperatures between 1023 and 1148 K at intervals of 25 K. In all these tests, the test temperatures were higher than the design temperature of 993 K. The stress level was kept constant at 105 MPa. The second series of creep rupture tests (series II) are conducted in a broad range of temperatures (923 to 1023 K) and stresses (100 to 600 MPa).

Results and Discussion

Rupture Life

Among the various methods followed for estimating residual creep life of service exposed components, isostress creep testing is considered to provide realistic estimates of the remanent

creep life[1]. This method involves conducting a batch of creep tests at temperatures greater than the service temperature and stress close to the service stress, and then extrapolating the rupture life-temperature data to the service temperature.

The isostress creep data at a stress level of 105 MPa obtained in this study is plotted in Fig.1. The value of 105 MPa has been arrived at after taking into account the hoop stress at the operating pressure of 14 MPa and the factor of safety assumed in the design. Rupture life increased linearly with decrease in temperature (on semilog plot) in the range of 1073 to 1148 K. Below 1073 K, the slope of the line changed very drastically and the life obtained at lower temperatures was much lower than that would be expected by extrapolation from the higher temperature region. This is in contrast to the behaviour generally exhibited by engineering materials which display a change in slope due to detrimental changes in the microstructure at high temperatures. Graphical extrapolation of the low temperature region of the trend line predicted a residual life of about 55000 hours at the service temperature of 993 K. Extrapolation based on the data for the temperature range 1073-1148 K predicted a residual life in excess of 200000 hours.



Fig.1. Variation of rupture life with temperature at 105 MPa (Isostress plot).

A Larson-Miller Parameter (LMP) analysis has been made of the combined rupture life data obtained from series I and II tests. Figure 2 shows the variation of LMP with stress (semi log plot). A value of 20.7 has been used for the constant C in the LMP equation, $LMP = T[C+logt_r]$ where t_r is the rupture life and T is the temperature in K. In the absence of reliable value for the constant C, a value of C=20 has been suggested for fitting the data[8]. The supplier of the tubes,

however, had used a value of 20.7 for extrapolation in their test report and so the same value has been chosen for the present analysis. A good statistical fit has been obtained with a correlation coefficient of R=0.97. Using Fig.2, a rupture life of 58000 hours has been predicted at 993 K at a stress of 105 MPa. This value compares favourably with the predicted value of 55000 hours from isostress experiments. Surprisingly, the predicted values of rupture life of material after service followed by this heat treatment are close to the failure time of 60000 hours of virgin material in service.



Fig.2. Larson-Miller Parameter plot of rupture data between 923 K and 1173 K.

Rupture Ductility

Figure 3 shows the variation of rupture elongation with temperature at a constant stress of 105 MPa. The material showed very good ductility at higher temperatures. But with a decrease in temperature, rupture ductility decreased drastically from a high of 70% at 1148 K to less than 20% at about 1098 K. Below 1098 K, ductility did not show any appreciable change with temperature. Analysis of the entire ductility data showed that at test temperatures of 1023 K and below, the ductility is generally around 20% and that it does not vary with stress or temperature. At temperatures above 1023 K, the ductility is high (40-65%) and that it decreases with increasing rupture life irrespective of the test temperature [Fig.4].







Fig. 4. Variation of rupture elongation with rupture life in the temperature range 973-1173 K. 809

Precipitation and Damage Behaviour

Detailed metallographic studies have been carried out on the creep damage and microstructural changes in the material. Wedge type of cracks have been generally observed at all the test conditions. Figure 5(a) shows typical creep damage observed at 1023 K with a rupture life of 170 hours, and the fracture surface of the specimen is shown in Fig. 5(b). Fracture appears to have taken place due to growth and linkage of cracks leading to plastic instability of the ligament between the intergranular cracks. Although Alloy 625 was originally developed as a solid solution



Fig.5. (a) Typical creep damage and (b) fracture surface of specimen tested at 1023 K; tr-170 h.

strengthened alloy, several studies have shown that the material is microstructurally unstable on elevated temperature exposure[2-7]. It has been reported that types MC, M_6C , $M_{23}C_6$ carbides and intermetallic phases (γ " and δ) precipitate in this alloy depending upon the temperature and duration of ageing. Gamma double prime, which is a metastable phase with an ordered body centred tetragonal crystal structure of Ni₃(Nb,Ti,Al) composition was noticed to precipitate in the temperature range 923 K to 1023 K. At temperatures higher than 1023 K, δ phase (a stable orthorhombic phase) with composition Ni₃(Nb) is generally observed [7].

The microstructural changes in the creep tested specimens have been studied using Scanning Electron Microscope. The samples were given electrolytic etching using chromic acid to reveal the intermetallic phases. Below 1023 K, there was no evidence of any matrix precipitation and only grain boundary precipitates were observed. At temperatures above 1023 K, profuse precipitation of δ phase, as identified by its acicular morphology, has been observed in the intragranular regions. Figure 6(a) shows δ phase needles within the grains and carbides along the boundaries after creep testing at 1098 K for 300 hours. As the test temperature increases, the size of the needles increased and their number density decreased. These morphological changes are clearly evident from Fig.6(b) to 6(f) which shows the microstructural changes due to ageing of the material for 500 hours at 873, 973, 1023, 1123 and 1173 K respectively. There was no evidence of matrix precipitation upto 973K whereas needle shaped δ phase particles were abundantly present at higher temperatures.



Fig.6. (a) Needle shaped delta-phase precipitates in specimen creep tested at 1098 K; t_r - 300 h. Microstructure after ageing for 500 hours at (b) 873 K, (c) 973 K, (d) 1023 K, (e) 1123 K and (f) 1173 K.

From the precipitation behaviour of the material observed in the present study, it is concluded that the two slope behaviour of the isostress curve (Fig.1) is due to the precipitation of intermetallic phases. The microstructural evidence suggests that the greater sensitivity of rupture life with temperature below 1073 K arises due to the precipitation of γ " phase. Although TEM studies have not been carried out, it is known from the literature that peak hardness of this material occurs when aged at 973 K due to precipitation of γ " phase[5,6]. It is suggested that the strengthening effect of γ " phase is also responsible for the lower ductility observed in below 1023 K (Figs. 2 and 3). Precipitation and growth of δ phase leads to loss of solid solution strengthening and order strengthening from γ ", and results in recovery of ductility.

Conclusions

- 1. Resolution annealing treatment was found to be beneficial to restore the creep rupture strength of service exposed Alloy 625 tubes.
- 2. Both isostress and LMP approaches predicted the same value of rupture life.
- 3. Rupture ductility was low at temperatures below 1023 K.
- 4. Precipitation of δ phase which took place at 1023 K and above had no detrimental effect on creep rupture ductility.

<u>References</u>

- 1. R. Viswanathan, Damage Mechanisms and Life Assessment of High Temperature Components (1990), p.59.
- 2. J.W. Brooks and P.J. Bridges, Superalloys 1988, S.Reichman, D.N. Dubil, G. Maurer, S. Antolovich and C Lund (eds.), The Metallurgical Society (1988) p.33.
- 3. L. Ferrer, B.Pieraggi and J.F.Uginet, Superalloys 718, 625 and Various Derivatives, Edward E Loria (ed.), The Minerals, Metals and Materials Society (1991) p.217.
- 4. M.Kohler, ibid, p.363.
- 5. R.Cozar, M.Rouby, B.Mayonobe and C.Morizot, ibid, p.423.
- 6. Chantal Vernot-Loirer and Francosis Cortial, ibid, p.409.
- 7. John F Radavich and Andrea Fort, ibid, p.635.
- 8. Ulrich Heubner and Michael Kohler, Superalloys 718, 625 and Various Derivatives, Edward E Loria (ed.), The Minerals, Metals and Materials Society (1994) p.479.